

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 056063	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 02/22/2025
NAME OF PROVIDER OR SUPPLIER Infinity Care of East Los Angeles		STREET ADDRESS, CITY, STATE, ZIP CODE 101 S Fickett Street Los Angeles, CA 90033	
For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)		
<p>F 0584</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>Honor the resident's right to a safe, clean, comfortable and homelike environment, including but not limited to receiving treatment and supports for daily living safely.</p> <p>**NOTE- TERMS IN BRACKETS HAVE BEEN EDITED TO PROTECT CONFIDENTIALITY** 48903</p> <p>Based on observation, interview and record review the facility failed to maintain the building in good repair and free from hazards in accordance with the facility's policy and procedure (P&P) titled Maintenance Service. The facility did not repair dark brown, moldy (covered with a fungal growth that causes decay, due to damp conditions) looking water damage and an opening in the ceiling of the second-floor dining room (Dinning room [ROOM NUMBER]). Furthermore, the facility did not close off Dining room [ROOM NUMBER] to residents upon discovering water damage and hole in ceiling.</p> <p>These deficient practices had the potential to expose residents to mold and debris from the opening in the ceiling roof of Dining room [ROOM NUMBER] which may cause illness to residents.</p> <p>Findings:</p> <p>During a concurrent observation and interview on 2/22/2025 at 8:18 AM with Certified Nursing Assistant (CNA) 1, the ceiling of Dining room [ROOM NUMBER] was observed. CNA 1 stated, there is peeling and brown discoloration on the ceiling. Like from water damage. It looks old. There is also a hole in the ceiling. They (maintenance) should have fixed it. It looks brown, dark color and could be mold.</p> <p>During a concurrent observation and interview on 2/22/2025 at 9:00 AM with Licensed Vocational Nurse (LVN) 1, the ceiling of Dining room [ROOM NUMBER] was observed. CNA 1 stated, there is moldy discoloration of the corner of the activity room. It looks old and is peeling. This exposes the residents to mold. They (the residents) have weakened immune systems and if they (the residents) are exposed to mold they can get an infection or get sick.</p> <p>During a concurrent observation and interview on 2/22/2025 at 9:12 AM with Registered Nurse (RN) 1, the ceiling of Dining room [ROOM NUMBER] was observed. RN 1 stated, there is a brown, moldy discoloration on the top right corner of the ceiling and a hole. It can cause illness to patients (the resident in the facility) if they are exposed to mold.</p> <p>(continued on next page)</p>		

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
FORM CMS-2567 (02/99) Previous Versions Obsolete	Event ID:	Facility ID: 056063
		If continuation sheet Page 1 of 2

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 056063	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 02/22/2025
NAME OF PROVIDER OR SUPPLIER Infinity Care of East Los Angeles		STREET ADDRESS, CITY, STATE, ZIP CODE 101 S Fickett Street Los Angeles, CA 90033	
For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)		
<p>F 0584</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>During a concurrent observation and interview on 2/22/2025 at 8:18 AM with CNA 2, the ceiling of Dining room [ROOM NUMBER] was observed. CNA 2 stated, there is brown moldy discoloration on the roof corner of the room. Residents come to watch television (TV) in this room. The ceiling is peeling off and I can see rotting wood inside. This is a health hazard (something that can cause harm to the health of people) because they can breathe in moldy air and get sick. The wall below the peeling ceiling looks like it has water damage, and the wood feels soft. It can easily break. There are water streaks on the paint and bubbling from water exposure. There is a resident in the room right now looking out the window.</p> <p>During a concurrent interview and record review on 2/22/2025 at 12:33 PM with the Maintenance Supervisor (MS), the facility's P&P titled, Maintenance Service, Revised 3/2024 was reviewed. The P&P indicated:</p> <ol style="list-style-type: none"> 1. Maintenance service shall be provided to all areas of the building, grounds and equipment. 2. The maintenance department is responsible for maintaining the buildings, grounds and equipment in a safe and operable manner at all times. 3. Functions of maintenance personnel include but are not limited to maintaining the building in good repair and free from hazards. <p>MS stated, I first noticed the hole and moldy discoloration on the ceiling of Dining room [ROOM NUMBER] on 2/18/2025 and documented it in my maintenance log. Nothing has been done to fix the hole in the room since then. The ceiling is not in good repair. It needs to be fixed soon. Our mistake is that we did not close the room to residents because the hole in the roof has debris that are falling, and residents can breathe it in and get sick.</p> <p>During a concurrent interview and record review on 2/22/2025 at 12:50 PM with the Administrator (ADM), the facility's Monthly Maintenance Inspection Check List (MMICL), dated 2/18/2025 was reviewed. MMICL indicated that Dining room [ROOM NUMBER] needs roof repaired. ADM stated, MS did notice the hole on the roof of Dining room [ROOM NUMBER] on 2/18/2025. The room should have been closed off sooner. The room was closed off today. The facility's policy for Maintenance Service indicated that the building should be kept in good repair and free of hazards.</p>		