

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155409	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 07/21/2025
NAME OF PROVIDER OR SUPPLIER Waters of Indianapolis, The		STREET ADDRESS, CITY, STATE, ZIP CODE 3895 S Keystone Ave Indianapolis, IN 46227	

For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)
<p>F 0921</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>Make sure that the nursing home area is safe, easy to use, clean and comfortable for residents, staff and the public.</p> <p>Based on observation and interview the facility failed to provide a safe and comfortable environment when the bathroom wall heater covers were removed leaving the metal heating elements exposed for 3 of 3 random observations; and failed to ensure the bathroom door frames were free from rust and decay for 2 of 3 random observations. Findings include:1. During a random observation of the secured memory care unit, on 7/21/25 from 8:25 a.m. until 9:05 a.m., observed the bathroom wall heaters in rooms H-8, H-10, and H-11. Each of the bathroom wall heaters were approximately six inches from the floor. The front cover of the heaters had been removed, which left approximately 40 small silver metal discs lined in a row across the inside of the heater exposed. During an interview, on 7/21/25 at 12:00 p.m., the Maintenance Supervisor indicated the heaters were still in working order and the heating elements should not have been left exposed to the residents. 2. During a random observation of the secured memory care unit, on 7/21/25 from 8:25 a.m. until 9:05 a.m., observed the bathroom door frames from inside the bathrooms of rooms H-10 and H-11. The door frame of room H-10's bathroom was metal with rusted areas on the left side of the frame. The frame had rusted away from the floor up approximately three inches, which left rusted jagged edges at the bottom of the rusted area toward the floor. The bathroom door frame of room H-11 had rusted areas on the right side of the frame. The frame had rusted away from the floor up approximately two inches, which left rusted jagged edges at the bottom of the rusted area toward the floor. During an interview, on 7/21/25 at 12:00 p.m., the Maintenance Supervisor indicated the bathroom door frames should not have been left rusted away. On 7/21/25 at 2:30 p.m., the facility was unable to provide a policy regarding the bathroom wall heaters or the rusted door frames. This citation relates to Complaint 1323958 3.1-19(f)</p>

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------