

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 195473	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 06/11/2024
NAME OF PROVIDER OR SUPPLIER Sterling Place Healthcare & Rehabilitation Center		STREET ADDRESS, CITY, STATE, ZIP CODE 3888 North Blvd Baton Rouge, LA 70806	

For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)
<p>F 0921</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Some</p>	<p>Make sure that the nursing home area is safe, easy to use, clean and comfortable for residents, staff and the public.</p> <p>39121</p> <p>Based on observations and interviews, the facility failed to provide a safe, sanitary, and comfortable environment in 12 of 12 (a, b, c, d, e, f, g, h, i, j, k, and l) rooms observed for environmental concerns.</p> <p>Findings:</p> <p>On 06/07/2024 at 12:10 p.m., an environmental tour was conducted with S2MAIN. S2MAIN confirmed the following findings:</p> <p>Room a</p> <p>-There was an approximate 1 gap in the right hand top corner between the air conditioner unit and the wall mount harness;</p> <p>Room b</p> <p>-Wires were hanging from the bottom of the telephone jack face plate cover;</p> <p>Room l</p> <p>-A hole was in the ceiling tile above the toilet;</p> <p>Room c</p> <p>-The edge of the bead board/paneling above the air conditioner unit was peeling away from the wall;</p> <p>Room d</p> <p>-An approximate 1/2 gap was between the air conditioner unit and the wall mount harness with outside light visible;</p> <p>-The edge of the bead board/paneling above the air conditioner unit was peeling away from the wall;</p> <p>Room e</p> <p>(continued on next page)</p>

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 195473	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 06/11/2024
NAME OF PROVIDER OR SUPPLIER Sterling Place Healthcare & Rehabilitation Center		STREET ADDRESS, CITY, STATE, ZIP CODE 3888 North Blvd Baton Rouge, LA 70806	
For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)		
<p>F 0921</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Some</p>	<p>-The bathroom vanity's laminate covering had peeled away from the right side. The bottom edge of the vanity's laminate covering was broken and rough;</p> <p>Room f</p> <p>-Stained ceiling tiles were near the window along the wall;</p> <p>-The cover of the air conditioner's power button was missing and the button covers for the temperature controls, mode, and speed were damaged;</p> <p>Room g</p> <p>-A rectangular hole was in the wall above the resident's bed on the right side wall;</p> <p>-A wall socket face plate cover was peeling from the wall near the resident's bed on the right side wall;</p> <p>-A wall socket face plate cover was broken on the wall near the bathroom;</p> <p>Room h</p> <p>-Ceiling tiles x2 were drooping above the resident's bed;</p> <p>-A ceiling tile was drooping over the toilet;</p> <p>Room k</p> <p>-A wall socket near the air conditioner unit was missing a face plate cover;</p> <p>Room i</p> <p>-The slats on the air conditioner unit were broken;</p> <p>Room j</p> <p>-An approximate 1/4 gap was between the air conditioner unit and the wall mount harness with outside light visible; and,</p> <p>-A wooden block was on the floor supporting the left hand side of the air conditioner unit.</p> <p>On 06/11/2024 at 12:10 p.m., an interview was conducted with S1ADM. S1ADM stated he was made aware of the aforementioned findings by S2MAIN and confirmed the findings should not be that way.</p> <p>On 06/11/2024 at 1:57 p.m., an observation was made of a bed in Room I with S1ADM. The head board of the bed was sitting on the bed frame leaning at an angle. The head board was missing one of the two metal brackets which allowed the headboard to be attached to the bed. S1ADM confirmed the head board was missing the bolts which held the brackets in place to support the head board to the bed frame. S1ADM confirmed the head board should not be like that.</p>		