

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 265827	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 03/20/2024
NAME OF PROVIDER OR SUPPLIER Bellevue Care Center		STREET ADDRESS, CITY, STATE, ZIP CODE 1616 Weisenborn Road Saint Joseph, MO 64507	

For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)
<p>F 0584</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>Honor the resident's right to a safe, clean, comfortable and homelike environment, including but not limited to receiving treatment and supports for daily living safely.</p> <p>**NOTE- TERMS IN BRACKETS HAVE BEEN EDITED TO PROTECT CONFIDENTIALITY** 44939</p> <p>Based on interview, observation and record review, the facility failed to maintain a safe, clean, comfortable homelike environment by not maintaining the ceilings in the memory care unit. This has the potential to affect all residents who reside on the memory care unit, 22 residents. The facility census was 82.</p> <p>The facility did not provide a policy regarding maintaining the environment.</p> <p>Observations of the memory care unit on 3/20/24 at 1:50 P.M., showed:</p> <ul style="list-style-type: none"> -A square, open hole, approximately 24 inches square, in the ceiling of the hall outside of room [ROOM NUMBER]. -A square, open hole, approximately 24 inches square, in the ceiling of area near the nurses' station. -Two square holes, approximately 12 inches square, covered with plastic sheeting, in the ceiling of the area leading from the nurses station to the dining area. -Five circular holes, approximately six inches in diameter, filled with plastic sheeting, in the ceiling of the area leading from nurses station to the dining area. <p>During an interview on 3/20/24 at 2:49 P.M., the Director of Maintenance said:</p> <ul style="list-style-type: none"> -He/she has worked at the facility for several years in the maintenance department, but recently became the Director of the department. -He/she was aware of the two larger holes. These two holes were cut in the ceiling by contractors, who needed access to the attic to fix pipes attached to the sprinkler system, which had frozen and burst. -He/she said the pipes broke in mid-February, but was unsure about an exact date. -He/she was unaware of the two smaller square holes and five circular holes in the ceiling of the memory care unit. <p>(continued on next page)</p>

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 265827	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED 03/20/2024
NAME OF PROVIDER OR SUPPLIER Bellevue Care Center		STREET ADDRESS, CITY, STATE, ZIP CODE 1616 Weisenborn Road Saint Joseph, MO 64507	
For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)		
<p>F 0584</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>-He/she is unsure when the contractors are going to be returning to the facility to fix the ceiling. The contractors are hired by the corporate office and out of southern Missouri.</p> <p>During an interview on 3/20/24 at 2:55 P.M., the Administrator said:</p> <p>-He/she was aware of the multiple holes in the ceiling of the memory care unit.</p> <p>-The contractors will be returning to the facility to repair the ceiling, but he/she is unaware of when they are scheduled to do the repairs.</p> <p>-It is his/her expectation that the facility be maintained, including repairing the ceilings.</p> <p>MO232791</p>		