

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  555700	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED  05/14/2025
NAME OF PROVIDER OR SUPPLIER  Beverly Hills Rehabilitation Centre		STREET ADDRESS, CITY, STATE, ZIP CODE  580 S San Vicente Blvd. Los Angeles, CA 90048	

For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)
<p>F 0689</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>Ensure that a nursing home area is free from accident hazards and provides adequate supervision to prevent accidents.</p> <p><b>**NOTE- TERMS IN BRACKETS HAVE BEEN EDITED TO PROTECT CONFIDENTIALITY** 44252</b></p> <p>Based on observation, interview and record review the facility failed to have one of four exit doors on the resident floors armed with an alarm that would sound when it was being opened.</p> <p>The failure had the potential to lead to a resident elopement (the act of leaving a facility unsupervised and without prior authorization) or accident.</p> <p>Findings:</p> <p>During an observation on 5/12/25 at 12:32 pm on the north side of the facility 's 1st floor, to the left of room [ROOM NUMBER], a exit door to the stairwell was observed with signage CAUTION ALARM IS ON EMERGENCY EXIT ONLY and signage in red OF EMERGENCY EXIT ALARM WILL SOUND IF DOOR IS OPENED. During the same observation a tall staff member with black scrubs was observed opening the door and entering the stairwell without an alarm sounding or the staff using a key to deactivate the alarm.</p> <p>During a concurrent observation and interview on 5/12/25 at 12:33 pm, with Certified Nursing Assistant (CNA) 1 the exit door to the stairwell next to room [ROOM NUMBER] was observed. CNA 1 stated she does not know why the exit door is not alarming as she opens the door and verifies it then states it should alarm when it is opened.</p> <p>During a concurrent observation and interview on 5/12/25 at 12:36 pm, with Housekeeping Supervisor (HKS) the exit door next to room [ROOM NUMBER] was observed being opened and keys being used to arm the door with the alarm and engage it, after several tries HKS stated it must be broken it is not alarming.</p> <p>During an interview with on 12:50 pm with the Director of Nursing (DON), the DON stated the risk of having the exit door not alarm when opened, is that someone that is confused could open it and then have an accident or fall.</p> <p>(continued on next page)</p>

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  555700	(X2) MULTIPLE CONSTRUCTION A. Building B. Wing	(X3) DATE SURVEY COMPLETED  05/14/2025
NAME OF PROVIDER OR SUPPLIER  Beverly Hills Rehabilitation Centre		STREET ADDRESS, CITY, STATE, ZIP CODE  580 S San Vicente Blvd. Los Angeles, CA 90048	
For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information)		
<p>F 0689</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p>	<p>During a review of the facility ' s policy and procedures revised January 2025 indicated Our facility strives to make the environment as free from accident hazards as possible. Resident safety and supervision and assistance to prevent accidents are facility-wide priorities . Safety risks and environmental hazards are identified no an ongoing basis through a combination of employee training, employee monitoring, and reporting processes . Employees shall be trained on potential accident hazards and demonstrate competency on how to identify and report accident hazards, and try to prevent avoidable accidents.</p>		