

| | | | |
|---|--|---|--|
| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 675440 | (X2) MULTIPLE CONSTRUCTION A. Building B. Wing | (X3) DATE SURVEY COMPLETED 03/16/2026 |
| NAME OF PROVIDER OR SUPPLIER South Dallas Nursing & Rehabilitation | | STREET ADDRESS, CITY, STATE, ZIP CODE 3808 S Central Expwy Dallas, TX 75215 | |

For information on the nursing home's plan to correct this deficiency, please contact the nursing home or the state survey agency.

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (Each deficiency must be preceded by full regulatory or LSC identifying information) |
|--|--|
| <p>F 0921</p> <p>Level of Harm - Minimal harm or potential for actual harm</p> <p>Residents Affected - Few</p> | <p>Make sure that the nursing home area is safe, easy to use, clean and comfortable for residents, staff and the public.</p> <p>Based on observation, interview and record review, the facility failed to provide a safe environment for residents, staff, and the public for one of two oxygen tanks observed for oxygen storage safety. The facility failed to securely store oxygen cylinders in the facility's one of two nurse's stations. This failure could affect the residents by placing them at risk of injury due to oxygen cylinders becoming unsecured and becoming a hazard. Findings included: Observation on 03/16/2026 at 10:57 a.m. revealed two oxygen cylinders next to the crash cart behind the nurse's station. One cylinder was secured in a rack, and one was not. Observation and interview on 03/16/2026 at 2:45 p.m. with LVN A revealed the oxygen tank was not secured. She stated she had just started her shift and did not notice it was unsecured. LVN A stated it should always be secured in a rack, and the risk was it was a hazard and could cause a fire. An interview on 03/16/2026 at 2:54 p.m. with the DON revealed she was not aware the tank was unsecured. She stated the night shift has been tasked with checking the crash carts and probably had changed it out and forgot to take it back to the storage room. She stated her expectation was that the tank should be secured at all times and the risk was it could get knocked over. She stated they did not have a policy on oxygen storage. Review of National Fire Protective Association, (NFPA) 99, 2012 Edition, Section 11.6.2.3, reflected: (11) Freestanding cylinders shall be properly chained or supported in a proper cylinder stand or cart .</p> |

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

| LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE |
|---|-------|-----------|
|---|-------|-----------|